



WESTERN RAILWAY EMPLOYEES' UNION

वेस्टर्न रेलवे एम्प्लॉईज यूनियन

(Regd., Recognized & Affiliated to AIRF & HMS)

AHMEDABAD DIVISION

Divisional Office :

1st Floor, Railway Station Building (BG), Railwaypura, Ahmedabad - 380002.
Phone : (P & T) 079 - 2217 1639 • (Rly.) (093) 41074, 41075, 41052, 41053, 41077
Fax : (093) 41049 (Rly.) • Email : wreu_adi@yahoo.co.in

President

R. C. Sharma

General
Secretary

R. Bhosale

Divisional
Chairman

S. K. Singh

Divisional
Vice Chairman

Haribux Singh

Harphool Kumavat

Ajit Gajjar

Divisional
Secretary

R. C. Sharma

Joint Divisional
Secretary

H. S. Pal

Dinesh Panchal

Divisional
Org. Secretary

G.K. Vyas

Divisional
Treasurer

R. S. Mishra

NO. ADI/DIVN/2015.

Dt. 16-5-2015.

To,

Sr. DOM/ADI.

Subj- Non-deploying required/sufficient
shunting staff by SS/VTAY for performing
shunting in ROH Depot, VTA Yard.

Dear Sir,

Of late, it is noticed that instead of deploying
minimum of 03 staff for carrying out shunting operation in
ROH Depot, only 02 staff and some times only 01 staff is
asked to do shunting work there.

Such deployment is not correct as far as safety in
shunting is concerned for the following reasons :-

1. The line in ROH Depot is not straight to warrant
less utilisation of staff.
2. No proper illumination in back side of yard is
provided.
3. No path is provided to ensure correct shunting
as the back portion is surrounded by thorny bushes and
surrounded by dirty nallah there.

Thus, it is quite evident from the above that
inadequate deployment of staff for any reason will lead to
compromise with safety. Also there should a clear cut guide
line as to how many Units/wagons are to be picked up in one
hook for shunting to bare minimum.

Action taken be advised.

Divisional Secretary,
WREU ADI.